



DEFENSE INFORMATION SYSTEMS AGENCY

P. O. BOX 4502
ARLINGTON, VIRGINIA 22204-4502

IN REPLY
REFER TO: Network Services (NS231)

01 Oct 2014

MEMORANDUM FOR DISTRIBUTION

SUBJECT: Department of Defense (DoD) Unified Capabilities (UC) Approved Products List (APL) approval of the Sonexis ConferenceManager Release (Rel.)10.0.40 Patch 8 Tracking Number (TN) 1022401 as a Conference Bridge (CB)

Reference: (a) DoDI 8100.04, "DoD Unified Capabilities," 09 Dec 2010.

1. DoD UC APL approval of the Sonexis ConferenceManager Release 10.0.40 Patch 8 TN 1022401 as a CB has been granted. The Field Security Operations (FSO) recommended certification on 20 Apr 2011 based on the security testing completed by Defense Information Systems Agency (DISA)-led Information Assurance test teams. This solution achieved Interoperability Certification (IOC) from the Joint Staff (JS) on 20 May 2011. This approval is effective upon the date of this memorandum and expires **30 Jul 2017** unless a critical issue is identified that invalidates either the Interoperability or the IA posture of this product as determined by the JS or the Defense Information Systems Network (DISN) Designated Approving Authority (DAA). Please note that Services and Agencies are required to recertify and reaccredit their systems every three years. Please refer to the UC APL for official posting of this solution at the following URL: <http://www.disa.mil/ucco>.

2. This product/solution must be implemented only in the configuration that was tested and approved. When the system is deployed into an operational environment, the following security measures (at a minimum) must be implemented to ensure an acceptable level of risk for the sites' DAA:

a. The site must register the system in the Systems Networks Approval Process (SNAP) Database <https://snap.dod.mil/index.cfm> as directed by the DSAWG and the Program Management Office (PMO).

b. The configuration must be in compliance with the Sonexis ConferenceManager Rel.10.0.40 Patch 8 TN 1022401's military-unique features deployment guide.

c. The system must be incorporated in the site's Public Key Infrastructure (PKI). If PKI is not incorporated, the following findings will be included in the site's architecture:

- APP3280 for ConferenceManager
- APP3290 for ConferenceManager
- APP3300 for ConferenceManager
- APP3305 for ConferenceManager
- DG0065 for ConferenceManager
- DSN13.17 for ConferenceManager
- NET0445 for ConferenceManager
- WG140 for ConferenceManager

DISA Memo, NS231, UC APL Approval Memo, Sonexis ConferenceManager Release 10.0.40 Patch 8 TN 1022401, 01 Oct 2014.

- WG145 for ConferenceManager

d. The system must use Active Directory (AD) or equivalent device for authentication and user account management.

e. The site must locate the solution behind the site's firewall.

f. The site must use the vendor's deployment guide to implement the settings for the solution's web interface.

3. The IOC letter containing detailed configuration on this product is available at the following URL: http://jitic.fhu.disa.mil/tssi/cert_pdfs/sonexiscm10_may11.pdf

On 03 Dec 2012, the following extension was approved via Desktop Review (DTR) #1 (to update from the certified release of 10.0.23 to 10.0.40 Patch 4):

http://jitic.fhu.disa.mil/tssi/cert_pdfs/sonexis_cm_10_0_dtr1_dec12.pdf

On 6 Jun 2014, the following extension was approved via DTR #2 (to update from the certified release of 10.0.40 Patch 4 to 10.0.40 Patch 8):

http://jitic.fhu.disa.mil/tssi/cert_pdfs/Sonexis_ConfMan_TN1022401_6Jun14.pdf

On 30 Jul 2014, the following extension was approved via DTR #3 (requested to extend this solutions listing on the UC APL for an additional 3 years)

On 11 Sep 2014, the following extension was approved via DTR #4 (requested to update hardware from an Intel SR2600 server system platform to the R1304JP4OC platform):

http://jitic.fhu.disa.mil/tssi/cert_pdfs/Sonexis_ConferenceManager_Rel_10_0_TN1022401_DTR_4_Sep14.pdf

4. Due to the sensitivity of the information, the Information Assurance Assessment Package (IAAP) that contained the approved configuration and deployment guide for this solution must be requested directly from the Unified Capabilities Certification Office (UCCO) by government civilian or uniformed military personnel.

E-Mail: disa.meade.ns.list.unified-capabilities-certification-office@mail.mil

UCCO Process Manager: (571) 359-4363

For:

JESSIE L. SHOWERS, JR., PMP
Vice Director for Network Services